











Reference numerals in the drawings

- 2 Printed circuit board
- 3 Soldering land for a coil end (outside a coil winding)
- 4 Soldering land for a coil end (inside a coil winding)
- 6 Disc-shaped rotor
- 7 Polarity
- 8, 9 Cross section of a coil
- 10 Center line of winding-bundle of a coil
- A Width of a winding-bundle of a coil
- HU, HV, HW position detector (magnetic sensor)
- U1, U2, V1, V2, W1, W2 coil
- Z A section where reversal torque is produced

blease delete page "4/4"

bluevad 12/13/12